Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Drilling of borewell and erecting pump and motor and providing MWS behind at ayyappa nagara in Jalahali
2	Administration Approval & Date	JC/RRNZ/AS/2951/2013-14 Dtd.05-03-2014 by JC (RRNZ)
3	Technical Sanction Estimate No.& Date	EE/RRND/TS/12/2014-15 Dtd: 16-06-2014 by EE(RRND)
4	Estimate Amount	Rs.8.00Lakhs
5	Job Code No.	016-14-000029
6	P-Code	P-2178
7	Agreement No & date	EE/RRND/AG.No./32/2014-15 Dtd.20-06-2014
8	Work order Number & Date	EE/RRND/Wo.No./32/2014-15 Dtd.20-06-2014
9	Contract Amount as per Agreement	Rs. 8,00,000/-
10	Bill Amount	Rs.8,87,690 /- including KRIDL Charges
11	B.R. No. & Date	285/2014-15 Dtd: 31-7-2014
12	Agency	KRIDL, Bangaluru
13	M.B. Number & Page No. of Measurement recordes	1812/14-15 Pages 181132 to 181143 (Xerox Copy of MB)
14	Date of Inspection	1-1-2016
15	Enclosures	1) 2 Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site along with the Concerned person. It is observed that one bore hole has been drilled and is Connected to the system for providing Drinking water to the residents of the area. The bore hole is functioning. This is a reference to the Xerox Copy of MB No 1812

s

EE (RRND) RR Nagara Zone

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ

(R.Sathyanarayana)
Inspection Report officer,